## Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION:

COUNTY:

DISTRICT:

148476

SEDO

American Energy Corp - Century Mine

43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716 Belmont

STATUS:

Original

PERMIT NUMBER: STATION CODE: MONITORING PERIOD: REPORTING LAB: 01L00091\*GD 008

2010-12-01 To: 2010-12-31

TraDet William Thompson

ANALYST: NO DISCHARGE INDICATOR:

PARAMETER	Manganese, Total (Mn)						
PARAMETER CODE	01055					<b>}</b>	
UNITS	ug/l						
FREQUENCY SAMPLING TYPE	1 / 2 Weeks				_	<del> </del>	
2010-12-01	Grab					<b></b>	
2010-12-02		_ <del></del>			<u> </u>	<u> </u>	<del></del>
2010-12-03	<del></del>				_	<b>}</b>	
2010-12-04	╂				- <del> </del>	\ <u></u>	
2010-12-05	\					{i	
2010-12-06	565		·				
2010-12-07							
2010-12-08							
2010-12-09	<u> </u>						
2010-12-10							
2010-12-11					<u> </u>		
2010-12-12					<u> </u>		
2010-12-13							
2010-12-14	<u> </u>						
2010-12-15						<u>                                     </u>	
2010-12-16							
2010-12-17							
2010-12-18							
2010-12-19							
2010-12-20	1310						
2010-12-21							
2010-12-22							
2010-12-23							
2010-12-24							
2010-12-25							
2010-12-26				<del></del>			
2010-12-27		Ì		*			
2010-12-28		1	ĺ				
2010-12-29			Ì				
2010-12-30			Ì				
2010-12-31			Ì				
Minimum	565.0						
Maximum	1310.0 937.5						
Average Count	937.3	<del></del> {			\	<del></del>	
Name of Responsible Official   certify under the penalty of law that I have personally examined and am familiar   Signature of Responsible Official or Authorized   Subm							
r Authorized Representative with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.  Page 3							2011-01- 12 20:01